



Refer to drawing 3482 - 001 for the park tree felling plan **CMP23, CMP24**

Refer to drawing 3482 - 004 for the proposed entrance works **CMP5, CMP7, CMP9, CMP10, CMP11,**

Refer to drawing 3482 - 005 for the proposed pathway improvements **CMP8, CMP13, CMP14, CMP15, CMP17, CMP18,**

Refer to drawing 3482 - 006 for a proposed park furniture and external lighting plan **CMP20, CMP21, CMP22, CMP36**

Refer to drawing 3482 - 007 for a proposed park planting strategy **CMP25, CMP26, CMP27**

**KEY**

- New hedge
- New planting
- New pathway
- New grassed area

**1.0 Entrances and Access Improvements**

- (refer to drawing 3482 - 004 for more detail)
- a Sutton Road / Stourport Road entrance **CMP11, CMP22**
  - b Stourport Road / Park Lane entrance **CMP10**
  - c Talbot Street / Park Lane entrance **CMP9, CMP22**
  - d Talbot Street (eastern entrance) **CMP7**
  - e Talbot Street (western entrance) **CMP6**
  - f Sutton Road / Talbot entrance **CMP6, CMP22**
  - g Sutton Road entrance **CMP5**

**2.0 Car park improvements**

- (refer to drawing 3482 - 004 for more detail)
- a Existing car park maintained (new permeable grid - topping up of gravel) **CMP19, CMP33, CMP34**
  - b New parking spaces (new permeable grid - gravel) **CMP19, CMP33, CMP34**
  - c New parking spaces (existing tarmac & patch repairs) **CMP19, CMP33, CMP34**
  - d New exit onto Sutton Road **CMP19, CMP33, CMP34**
  - e Existing parking removed from main driveway **CMP5**
  - f Overflow car park

**3.0 Maintenance yard improvements **CMP34****

- (refer to drawing 3482 - 031 for more detail)
- a New bin store **CMP19**
  - b New store **CMP19**

**4.0 Senses Garden improvements**

- (refer to drawing 3482 - 011 for more detail)
- a New cafe **CMP28, CMP29**
  - b New surfacing (permeable grid - gravel)

**5.0 Emily Jordan Foundation improvements**

- (refer to drawing 3482 - 041 for more detail)
- a Refurbished toilets **CMP28**
  - b Relocated polytunnel (from maintenance yard) **CMP32**
  - c Refurbished Victorian Bothy **CMP31**

**6.0 Sons of Rest Pavilion improvements**

- (Refer to drawing 3482 - 022 for more detail)
- a Extension to pavilion **CMP30**
  - b New verandah terrace **CMP35**

**7.0 Pool reinstatement**

- a Reinstated pool. Coir roll edges as indicated, shallow edges along southern side **CMP12**
- b Timber bridge **CMP13**

**8.0 WC block improvements**

- (Refer to drawing 3482 - 052 for more detail)
- a WC refurbished **CMP29**

**9.0 Street Furniture improvements**

- a Bandstand: Refurbish the existing bandstand; concrete painting, new panel banners, soil works at front of bandstand to stop pools of water forming **CMP2**
- b Richard Eve Memorial: Repair works to memorial, benches around memorial removed and placed elsewhere in the park **CMP1**
- c Bird sculpture
- d Bandstand seating

**10.0 Pathway improvements**

- (Refer to drawing 3482 - 005 for more detail)
- a Pathway removed **CMP14**
  - b Section of pathway reshaped to better reflect the bandstand **CMP14**
  - c Reinforce grass between path and bandstand with 'turfmesh' **CMP14**
  - d New pathway (linking Talbot Street to tennis court area) **CMP7**
  - e New cemetery pathway: modern handrail removed, restore cemetery boundary brickwork **CMP8, CMP18**
  - f New pathway in place of existing hedge (linking the car park to the playground area) **CMP19**
  - g New section of pathway (to north of reinstated pool) **CMP12, CMP15**
  - h New steps & pathway linking entrance drive to senses garden **CMP14**
  - i New section of pathway linking cafe to stores in maintenance yard **CMP14**

**11.0 Landscape improvements**

- a Grassed area (in place of existing driveway) **CMP26**
- b Planting to perimeter of proposed cafe **CMP26, CMP27**
- c New planting area to EJF area (works not in main contract) **CMP26, CMP27**
- d Mixed shrubbery to front of Sons of Rest Pavilion **CMP26, CMP27**
- e New planting: 'The Dell' - foliage plants **CMP25, CMP26**
- f New shrubbery adjacent to new pathway **CMP26**
- g New low perennial planting (between existing benches) **CMP26**
- h New mixed flower beds **CMP26**
- i New hedge (holly) **CMP26**
- j New wildflower meadow **CMP25, CMP26**
- k New edge planting to pool area **CMP25, CMP26**
- l New grass verges to pool area **CMP12**
- m Marginal planting to water edges of reinstated pool **CMP25, CMP26**
- n New small planting beds to Sutton Road / Stourport Road entrance **CMP26**
- o New planting bed to base of fence **CMP26**
- p New planting bed to Stourport Road / Park Lane entrance **CMP26**

**12.0 Woodland management improvements**

- a Stump garden: habitat for hedgehog, reptile & invertebrates **CMP25**
- b Historic Native Meadow and native bee hotel: creation of an acidic grassland & the building of a bee bank **CMP25**

Note: Woodcrete bat boxes to be located into the larger trees, including at least one maternity roost box. Predator boxes to be included on some of the larger trees around the south of the site.